



Government Of West Bengal  
Office Of The Divisional Fire Officer, Paschim Bardhaman  
West Bengal Fire & Emergency Services  
Asansol Fire Station, G.T. Road, P.O.: -Asansol,  
P.S.: -Asansol(South), Pin :- 713301

Date: 20-11-2023

Memo no.: FSR/0125186230300247

From:  
Divisional Fire Officer, Paschim Bardhaman  
West Bengal Fire & Emergency Services

To: DISHARI COLLEGE OF EDUCATION (BARDHAMAN CYBER RESEARCH & TRAINING INSTITUTE)  
PLOT NO. - 172, 173, KH. NO. - 241, JL. NO. - 073, MOUZA - DANGACHA, KALNA ROAD, NADRA, UNDER  
BAIKUNTHAPUR - 1, GRAM PANCHAYET, PIN - 713101, PURBA BARDHAMAN.

Sub: FIRE SAFETY CERTIFICATE OF AN EXISTING (G+3) STORIED EDUCATIONAL BUILDING. Under Group-  
"B"(EDUCATIONAL BUILDING) at over PLOT NO. - 172, 173, KH. NO. - 241, JL. NO. - 073, MOUZA - DANGACHA,  
KALNA ROAD, NADRA, UNDER BAIKUNTHAPUR - 1, GRAM PANCHAYET, PIN - 713101, PURBA BARDHAMAN. In  
the name & style "DISHARI COLLEGE OF EDUCATION (BARDHAMAN CYBER RESEARCH & TRAINING  
INSTITUTE)+.

This is in reference to your application no. 0125189230300092 dated 01-11-2023 regarding the FIRE SAFETY  
CERTIFICATE OF AN EXISTING (G+3) STORIED EDUCATIONAL BUILDING. Under Group-"B"(EDUCATIONAL  
BUILDING) at over PLOT NO. - 172, 173, KH. NO. - 241, JL. NO. - 073, MOUZA - DANGACHA, KALNA ROAD, NADRA,  
UNDER BAIKUNTHAPUR - 1, GRAM PANCHAYET, PIN - 713101, PURBA BARDHAMAN. In the name & style "DISHARI  
COLLEGE OF EDUCATION (BARDHAMAN CYBER RESEARCH & TRAINING INSTITUTE)+.

The performance of the Fire Fighting System as incorporated in the buildings were tested at random and found  
satisfactorily working condition. In view of the above this office is releasing the Fire Safety Certificate for occupancy of the  
aforesaid building.

**Recommendation:**

RECOMMENDATION: -

NOTE - F.S.C. has been issued on condition that one standby pump, D.G. set, Detection system should be installed within  
six month and inform to this Department in written.

1.A Stand by Pump (LPM 1250) Diesel Driven should be provided.2. Sufficient Yard Hydrant should be installed around the  
building.3. Sufficient Fire Extinguisher should be kept.4.UGWR should be provided at least 50000ltrs capacity. Driveway